

Phone : +(242) 05 377 95 54
 +(242) 05 377 95 64
 AFTN : FCCCYNYX
 E-mail : bnibrazza@yahoo.fr
 : bnibrazza@asecna.org
 Web : <https://aim.asecna.aero>



**BUREAU NOTAM INTERNATIONAL
 DE L'AFRIQUE CENTRALE**

B.P. 660 BRAZZAVILLE - CONGO

**AIP SUP
 NR 30/A/21FC
 07 JUL 2021**

CAMEROUN – CENTRAFRIQUE – CONGO – GABON – GUINEE ÉQUATORIALE – SAO TOME – TCHAD

BANGUI M'POKO (CENTRAL AFRICAN REPUBLIC) REPLACEMENT OF NOTAM

Effective date	07 JUL 2021
Validity	31 DEC 2021

Suite à l'atelier sur l'amélioration des NOTAM (NOTAM 2021) visant à diminuer la prolifération des NOTAM dans la région WACAF, les NOTAM Suivants sont remplacés par ce présent SUP AIP :
 A0892/21, A0888/21, A0887/21, A0886/21, A0885/21, A0884/21, A0704/21, A0651/21, A0650/21, A0572/21, A0483/21, A0352/21 et A0351/21

Following the workshop on improving NOTAMs (NOTAM 2021) aimed at reducing the proliferation of NOTAM in the WACAF region, The following NOTAMs are replaced by this AIP SUP : A0892/21, A0888/21, A0887/21, A0886/21, A0885/21, A0884/21, A0704/21, A0651/21, A0650/21, A0572/21, A0483/21 A0352/21 and A0351/21

NR	OBJECT	LOCATION	REMARKS
1	AERODROME	FEFF	RISK OF DISRUPTION OF ATM, MET AND AGA SERVICE AT BANGUI AIRPORT DUE TO AUXILIARY POWER SUPPLY SUBJECT TO INTERRUPTION
2	AUTONOMOUS LGT	FEFF	NIGHTS LDG AND TKOF PROHIBITED DUE TO REDUCTION OF THE NUMBER OF AUTONOMOUS LIGHTS.
3	WIP	FEFF	WORK IN PROGRESS AROUND THE RWY 34. CONSTRUCTION OF METEOROLOGICAL PARK AND FIRE STATION. PRESENCE OF WORKERS AND EQUIPMENTS. CAUTION ADVISED WHEN LDG AND TKOF
4	COVID-19	FEFF	DUE TO COVID-19 PANDEMIC AND THE DROP OF AIR TRAFFIC IN ASECNA SPACE, ALL AIRLINES WISHING TO SERVE BANGUI M'POKO AIRPORT IN ACCORDANCE WITH NOTAM A0885/21 ARE REQUIRED TO FILL FPL 24 HOURS BEFORE EOBT

5	BANGUI M'POKO AD	FEFF	BANGUI M'POKO INTERNATIONAL AIRPORT IS GRADUALLY REOPENED TO ALL INTERNATIONAL FLIGHTS. HOWEVER COMMERCIAL PASSENGER FLIGHT ARE AUTHORIZED ON THE BASIS OF ONE FLIGHT PER WEEK AND COMPANY ON DEPARTURE AND ARRIVAL. ALL PASSENGERS ON DEPARTURE AND ARRIVAL ARE SUBJECT TO THE BARRIER MEASURES ISSUED BY THE CENTRAL AFRICAN GOVERNMENT FOR THE FIGHT AGAINST COVID-19
6	CURFEW	FEFF	CURFEW AT BANGUI - AD OPR
7	THRESHOLD	FEFF	UNEVEN OF ABOUT 5 CM ON THE RWY AT 880 METERS FROM THE THRESHOLD 34. CAUTION ADVISED
8	BIRD CONCENTRATION	FEFF	BIRD CONCENTRATION AROUND RWY 16/34. CAUTION ADVISED
9	WIND DIRECTION INDICATOR RWY 16	FEFF	UNSERVICEABLE
10	RWY	FEFF	PRESENCE OF NEIGHBOURING POPULATION AROUND RWY16/34 CAUTION ADVISED
11	SIOMA	FEFF	SIOMA EQUIPMENT WORKS PARTIALLY : WIND SENSOR AND TEMPERATURE SENSOR U/S WIND SENSOR : USE SENSOR EARTH SYSTEM NETWORK TEMPERATURE SENSOR : TEMPERATURE OF METEOROLOGICAL PARK
12	TWR VHF	FEFF	TWR VHF 119.7MHZ RANGE LIMITED IN EAST PART DUE TO MOUNTAINS
13	NDB 'BN' 265.5KHZ	FEFF	UNSERVICEABLE

CE SUP AIP CONTIENT 02 PAGES/ THIS AIP SUP INCLUDES 02 PAGES