

Tel : +(261) 20.22.581.13  
 +(261) 20.22.581.14  
 +(261) 33.23.370.01

Fax : NIL

AFTN : FMMMYNYX

E-mail : bnitan@asecna.org  
 AntananarivoNOF@gmail.com

Web : https://aim.asecna.aero



**BUREAU NOTAM INTERNATIONAL  
 D'ANTANANARIVO**

**B.P. 46 Ivato Aéroport Antananarivo -  
 MADAGASCAR**

**AIP SUP  
 NR 25/B/23FM  
 19 OCT 2023**

**LA REUNION\* - MADAGASCAR - MAYOTTE\* - UNION DES COMORES**

\* The AIC, AMDT, AIP and AIP SUP concerning these islands are published on <https://sia.aviation-civile.gouv.fr>

**FMSM**

**NIVEAU DE PROTECTION SSLI DÉCLASSÉ À UN  
 RFFS PROTECTION LEVEL DOWNGRADED TO ONE**

<i>Effective date :</i>	<b>19 OCT 2023</b>
<i>Validity :</i>	<b>30 JUN 2025 EST</b>

Suite à l'atelier organisé par l'OACI en juin 2021 sur l'amélioration des NOTAM, qui vise à diminuer la prolifération des NOTAM dans la région ESAF, l'information contenue dans le NOTAM B0286/23 qui concerne l'aérodrome de MANANJARY est incorporée dans le présent SUP AIP :

Following the workshop organized by ICAO in June 2021 on improving NOTAM, that aims to reduce the proliferation of NOTAM in the ESAF region, the information contained in the NOTAM B0286/23 that concerns MANANJARY aerodrome is incorporated in this AIP SUP :

*Le niveau de protection SSLI est déclassé à un (1)  
 à cause de l'indisponibilité du véhicule VIMP .*

*RFFS PROTECTION LVL DOWNGRADED TO ONE (1)  
 DUE TO 'VIMP' VEHICLE NOT AVBL.*

THIS AIP SUP HAS 01 PAGE