

Tel : +(261) 20.76.581.13

+(261) 33.23.370.01

Fax : NIL

AFTN : FMMMYNYX

E-mail : aim-fmmm@asecna.org

AntananarivoNOF@gmail.com

Web : <https://aim.asecna.aero>



**BUREAU NOTAM INTERNATIONAL
D'ANTANANARIVO**

**B.P. 46 Ivato Aéroport Antananarivo -
MADAGASCAR**

**AIP SUP
NR 05/B/26FM
18 FEB 2026**

LA REUNION* - MADAGASCAR - MAYOTTE* - UNION DES COMORES

* The AIC, AMDT, AIP and AIP SUP concerning these islands are published on <https://sia.aviation-civile.gouv.fr>

AIP SUP 30/B/24FM IS REPLACED BY THIS AIP SUP

FMMV

ETAT DU PAPI PISTE 10

STATUS OF THE RWY 10 PAPI (U/S)

<i>Effective date :</i>	18 FEB 2026
<i>Validity :</i>	31 DEC 2026 EST

L'indicateur de trajectoire d'approche de précision (PAPI) dont les caractéristiques figurent dans le tableau ci-après est **hors service** :

The precision approach path indicator (PAPI) whose characteristics are shown in the following table is **unserviceable** :

AERODROME	FACILITY	RUNWAY	STATUS
MORONDAVA (FMMV)	PAPI	RWY 10	U/S

THIS AIP SUP HAS 01 PAGE