

Phone : +(242) 05 377 95 54  
 +(242) 05 377 95 64  
 AFTN : FCCCYNYX  
 E-mail : bnibrazza@yahoo.fr  
 : bnibrazza@asecna.org  
 Web : https://aim.asecna.aero



**BUREAU NOTAM INTERNATIONAL  
 DE L'AFRIQUE CENTRALE**

**B.P. 660 BRAZZAVILLE - CONGO**

**AIP SUP  
 NR 32/A/21FC  
 08 JUL 2021**

**CAMEROUN – CENTRAFRIQUE – CONGO – GABON – GUINEE ÉQUATORIALE – SAO TOME – TCHAD**

## EQUATORIAL GUINEA REPLACEMENT OF NOTAM

<b>Effective date</b>	<b>08 JUL 2021</b>
<b>Validity</b>	<b>31 DEC 2021</b>

Suite à l'atelier sur l'amélioration des NOTAM (NOTAM2021) visant à diminuer la prolifération des NOTAM dans la région WACAF, les NOTAM Suivants sont remplacés par ce présent SUP AIP :  
 A0890/21, A0621/21, A0642/21, A0558/21, A0609/21, B0035/21, B0043/21, B0060/21 et B0062/21

*Following the workshop on improving NOTAM(NOTAM2021) aimed at reducing the proliferation of NOTAM in the WACAF region, The following NOTAM are replaced by this AIP SUP : A0890/21, A0621/21, A0642/21, A0558/21, A0609/21, B0035/21, B0043/21, B0060/21 and B0062/21*

NR	OBJECT	LOCATION	REMARKS
1	GPS	FGSL	GPS SIGNAL SUBJECT TO INTERRUPTION
2	RWY	FGBT	WIP AT 70 M FROM RWY 03/21 RIGHT EDGE. CAUTION ADVISED WHEN LDG AND TKOF
3	RWY 03/21 CENTER LINE LGT	FGBT	UNSERVICEABLE
4	ILS LOC 'BA' 109.10 MHZ	FGBT	OPERATIONAL ON ONE SET
5	NDB "BT" 325 KHZ	FGBT	UNSERVICEABLE
6	ILS GP 'MBO' 333.2 MHZ	FGSL	UNSERVICEABLE
7	ILS LOC "MBO" 109.7 MHZ	FGSL	UNSERVICEABLE - ILS PROCEDURE PROHIBITED
8	RWY	FGSL	WIP AROUND RWY 04/22. PRESENCE OF WORKERS AND MACHINES. CAUTION ADVISED WHEN LDG AND TKOF.
9	ILS DME 'MBO' CH34X	FGSL	UNSERVICEABLE
10	ILS GP "BA" 331.40 MHZ	FGBT	OPERATIONAL ON ONE SET
11	COVID-19	FGXX	COVID-19 1- INTERNATIONAL FLIGHT TO ALL AIRLINES OPERATING IN EQUATORIAL GUINEA ARE AUTHORIZED AT THE RATE OF ONE WEEKLY FLIGHT PER COMPANY. 2- PASSENGERS AND CREWS ARRIVING IN MALABO MUST PRESENT A NEGATIVE PCR TEST CERTIFICATE VALID FOR 48 HOURS, HOWEVER A QUICK TEST WILL BE CARRIED OUT AT THE AIRPORT, IN CASE OF NEGATIVE PASSENGERS MUST PASS A COMPULSORY QUARANTINE

			<p>OF 5 DAYS, IN CASE OF POSITIVE PASSENGERS MUST PASS A QUARANTINE OF 14 DAYS.</p> <p>3-NATIONAL AIRLINES ARE AUTHORIZED THREE INTERREGIONAL WEEKLY FLIGHT. FOR ADITIONAL FLIGHT AIRLINES MUST REQUEST SPECIAL AUTHORIZATION.</p> <p>4- ALL FLIGHT MUST ABIDE BY ALL PANDEMIC PREVENTION MEASURES ISSUED BY THE WORLD HEALTH ORGANIZATION</p>
12	ILS/GP 'MY' 333.8MHZ	FGMY	UNSERVICEABLE
13	ILS/LOC 'MY' 109.9MHZ	FGMY	UNSERVICEABLE- ILS PROCEDURES PROHIBITED
14	DVOR 'MBO' 114.5MHZ	FGSL	OPERATES ON ONE SET

**CE SUP AIP CONTIENT 02 PAGES/ THIS AIP SUP INCLUDES 02 PAGES**