

Phone : +(242) 05 377 95 54
 +(242) 05 377 95 64
 AFTN : FCCCYNYX
 E-mail : bnibrazza@yahoo.fr
 : bnibrazza@asecna.org
 Web : https://aim.asecna.aero



**BUREAU NOTAM INTERNATIONAL
 DE L'AFRIQUE CENTRALE**

B.P. 660 BRAZZAVILLE - CONGO

**AIP SUP
 NR 18/A/22FC
 15 FEB 2022**

CAMEROUN – CENTRAFRIQUE – CONGO – GABON – GUINEE ÉQUATORIALE – SAO TOME – TCHAD

**EQUATORIAL GUINEA
 (FGXX)**

Effective date	15 FEB 2022
Validity	31 DEC 2022

Ce Supplément d'AIP informe les usagers sur :

- L'indisponibilité des Aides de Radionavigation et d'atterrissage
- les travaux en cours sur certaines pistes

This AIP Supplement informs users about :

- *The unavailability of Radio navigation and landing aids*
- *and work in progress on certain runways*

NR	OBJECT	LOCATION	INFORMATIONS/REMARKS
1	GPS	FGSL	GPS SIGNAL SUBJECT TO INTERRUPTION
2	ILS GP 'MBO' 333.2 MHZ	FGSL	UNSERVICEABLE
3	ILS LOC "MBO" 109.7 MHZ	FGSL	UNSERVICEABLE - ILS PROCEDURE PROHIBITED
4	ILS DME 'MBO' CH34X	FGSL	UNSERVICEABLE
5	RWY	FGSL	WIP AROUND RWY 04/22. PRESENCE OF WORKERS AND MACHINES. CAUTION ADVISED WHEN LDG AND TKOF.
6	TWY'D'	FGSL	CLOSED DUE TO WIP
7	RWY	FGBT	WIP AROUND RWY 03/21 PRESENCE OF WORKERS AND MACHINES. CAUTION ADVISED WHEN LDG AND TKOF. CAUTION ADVISED WHEN LDG AND TKO
8	ILS LOC 'BA' 109.10 MHZ	FGBT	OPERATIONAL ON ONE SET
9	ILS/GP 'MY' 333.8MHZ	FGMY	UNSERVICEABLE
10	ILS/LOC 'MY' 109.9MHZ	FGMY	UNSERVICEABLE- ILS PROCEDURES PROHIBITED
11	VOR/DME "ANN" 114.1Mhz/CH88X	FGAN	UNSERVICEABLE

CE SUP AIP CONTIENT 01 PAGE/ THIS AIP SUP INCLUDES 01 PAGE