

Phone : +(242) 05 377 95 54
 +(242) 05 377 95 64
 AFTN : FCCCYNYX
 E-mail : bnibrazza@yahoo.fr
 : bnibrazza@asecna.org
 Web : https://aim.asecna.aero



**BUREAU NOTAM INTERNATIONAL
 DE L'AFRIQUE CENTRALE**

B.P. 660 BRAZZAVILLE - CONGO

**AIP SUP
 NR 62/A/23FC
 13 JUL 2023**

CAMEROUN – CENTRAFRIQUE – CONGO – GABON – GUINEE ÉQUATORIALE – SAO TOME – TCHAD

EQUATORIAL GUINEA

**Certaines informations aéronautiques/
 Some aeronautical information**

THIS AIP SUP CANCELS AND REPLACES AIP SUP NR 61/A/23FC

<i>Effective date</i>	13 JUL 2023
<i>Validity</i>	31 DEC 2023

Ce supplément d'AIP informe les usagers sur l'indisponibilité des aides de radionavigation et d'atterrissage, et sur les travaux en cours sur certaines pistes.	<i>This AIP Supplement inform users about the unavailability of radio navigation and landing aids, and work in progress on certain runways.</i>
---	---

NR	OBJECT	LOCATION	REMARKS
1	GPS	FGSL	GPS SIGNAL SUBJECT TO INTERRUPTION
2	ILS GP "MBO" 333.2 MHZ	FGSL	UNSERVICEABLE
3	ILS LOC "MBO" 109.7 MHZ	FGSL	UNSERVICEABLE. ILS PROCEDURE PROHIBITED
4	ILS DME "MBO" CH34X	FGSL	UNSERVICEABLE
5	RWY	FGSL	WIP AROUND RWY 04/22. PRESENCE OF WORKERS MACHINES. CAUTION ADVISED WHEN LDG AND TKOF.
6	ILS LOC "BA" 109.10 MHZ	FGBT	OPERATE ON ONE SET
7	ILS GP "BA" 331.4 MHZ	FGBT	UNSERVICEABLE
8	DME "BTA" CH 101X	FGBT	OPERATE ON ONE SET
9	RWY	FGBT	WIP AROUND RWY 03/21. PRESENCE OF WORKERS MACHINES. CAUTION ADVISED WHEN LDG AND TKOF
10	ILS/LOC "MY" 109.9 MHZ	FGMY	UNSERVICEABLE. ILS PROCEDURE PROHIBITED
11	ILS/GP "MY" 333.8 MHZ	FGMY	UNSERVICEABLE
12	DVOR/DME "MGY" 114.3 MHZ/CH90X	FGMY	UNSERVICEABLE
13	VOR/DME "ANN" 114.1 MHZ/CH88X	FGAN	UNSERVICEABLE

CE SUP AIP CONTIENT 01 PAGE/ THIS AIP SUP INCLUDES 01 PAGE