

Phone : +(221) 77.519.79.01
 +(221) 33.957.49.37
 Fax : +(221) 33.820.06.00
 AFTN : GOOYNYX
 E-mail : bnidak@asecna.org
 Web : <https://ais.asecna.aero>



AIP SUP
NR 75/A/22GO
MAY 30 , 2022

BUREAU NOTAM INTERNATIONAL DE L'OUEST AFRICAIN
 B.P. 8155 Aéroport International Blaise DIAGNE Dakar/Diass-SENEGAL

BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER – SENEGAL – TOGO

ONDULEUR HORS SERVICE A L'AERODROME DE LOME

UNINTERRUPTIBLE POWER SUPPLY UNSERVICEABLE AT LOME AERODROME

DXXX

/

TOGO

Mise en vigueur/ Effective Date	30 Mai 2022, <i>May 30 2022</i>
Validité/ Validity	31 Décembre 2022, <i>December 31 2022</i>

CE SUPPLEMENT ANNULE ET REMPLACE LE NOTAM GOOO C0067/22, DGAA A0071/22

THIS SUPPLEMENT CANCELS AND REPLACES NOTAM GOOO C0067/22, DGAA A0071/22

AERODROME AERODROME	ALIMENTATION ELECTRIQUE AUXILIAIRE/ SECONDARY POWER SUPPLY	ETAT/ STATUS
LOME	ONDULEUR / UNINTERRUPTIBLE POWER SUPPLY	HORS SERVICE / UNSERVICEABLE
REGULATION/ REGULATION		
LE "SECOURS INVERSÉ" EST EN SERVICE / "EMERGENCY INVERSE" IN SERVICE		

FIN/ END