

Phone : +(242) 05 377 95 54

+ (242) 05 377 95 64

AFTN : FCCCYNYX

E-mail : bnibrazza@asecna.org

bnibrazza@yahoo.fr

Web : <https://aim.asecna.aero>



**BUREAU NOTAM INTERNATIONAL  
DE L'AFRIQUE CENTRALE**

B.P. 660 BRAZZAVILLE – CONGO

**AIP SUP  
NR 86/A/22FC  
18 OCT 2022**

CAMEROUN – CENTRAFRIQUE – CONGO – GABON – GUINEE ÉQUATORIALE – SAO TOME – TCHAD

## PORT-GENTIL (GABON)

### ETAT DE FONCTIONNEMENT DE CERTAINES AIDES D'ATERRISSAGE / *OPERATIONAL STATUS OF SOME LANDING AIDS*

CE SUP AIP ANNULE LES NOTAM A1130/22, A1132/22, A1133/22, A1134/22 ET  
A1135/22 /

*THIS AIP SUP CANCELS NOTAM A1130/22, A1132/22, A1133/22, A1134/22 AND  
A1135/22.*

<b>DATE EFFECTIVE/EFFECTIVE DATE</b>	18 OCT 2022
<b>VLIDITE/VALIDITY</b>	01 JAN 2023

Information en vigueur sur l'aérodrome de PORT-GENTIL notamment sur l'état de fonctionnement de certaines aides d'atterrissage est indiqué comme suit :	<i>Information in force at the PORT-GENTIL aerodrome in particular about the operational status of some landing aids is indicated below:</i>
--	--

NR	OBJET /OBJECT	OBSERVATIONS/OBSERVATIONS	HORAIRE/HOURS
1	ILS/DME 'PO' Ch28X	HORS SERVICE /UNSERVICEABLE	H24
2	ILS/LOC 'PO' 109.1MHz	HORS SERVICE /UNSERVICEABLE	H24
3	ILS/GP 'PO' 331.4MHz	HORS SERVICE /UNSERVICEABLE	H24
4	PAPI QFU 21	HORS SERVICE /UNSERVICEABLE	H24
5	NDB 'PG' 367kHz	HORS SERVICE /UNSERVICEABLE	H24

**CE SUP AIP CONTIENT 01 PAGE / THIS AIP SUP INCLUDES 01 PAGE**