

Phone : +(221) 77.519.79.01  
 +(221) 33.957.49.37  
 Fax : +(221) 33.820.06.00  
 AFTN : GOOOYNYX  
 E-mail : dakarbni@asecna.org  
 Web : <https://aim.asecna.aero>



AIRAC AIP SUP  
 NR 59/A/21GO  
 JUNE 16, 2021

**BUREAU NOTAM INTERNATIONAL DE L'OUEST AFRICAIN**  
 B.P. 8155 Aéroport International Blaise DIAGNE Dakar/Diass-SENEGAL

**BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER – SENEGAL – TOGO**

**CREATION DE TROIS ZONES INTERDITES A COTONOU**

*CREATION OF THREE PROHIBITED AREAS AT COTONOU*

/

**BENIN**

<b>Mise en vigueur/Effective Date</b>	15 juillet 2021/July 15, 2021
<b>Validité/Validity</b>	PERM

ENR 5.1 ZONES INTERDITES, RÉGLEMENTÉES OU DANGEREUSES

*PROHIBITED, RESTRICTED AND DANGER AREAS*

IDENTIFICATION, NOM ET LIMITES LATÉRALES Identification, name and Lateral Limits	LIMITES SUPÉRIEURES	OBSERVATIONS / Remarks (Heures d'activité, Genre de limitation, Nature des dangers, Risque d'interception) (Time of activity, Type of restriction, Nature of hazard, Risk of interception)
	LIMITES INFÉRIEURES Upper / Lower Limits	
1	2	3
<b>ZONES INTERDITES / PROHIBITED AREAS</b>		
<b>DBP 5 COTONOU</b>  06°21'12"N - 002°24'29"E, 06°21'11"N - 002°24'44"E, 06°21'01"N - 002°24'37"E, 06°21'01"N - 002°24'29"E, 06°21'12"N - 002°24'29"E,	FL 035 ----- SOL	Survol interdit Overflight Prohibited
<b>DBP 6 COTONOU</b>  06°21'38"N - 002°24'33"E, 06°21'34"N - 002°24'40"E, 06°21'28"N - 002°25'05"E, 06°21'24"N - 002°25'03"E, 06°21'25"N - 002°24'27"E, 06°21'29"N - 002°24'27"E, 06°21'37"N - 002°24'42"E, 06°21'38"N - 002°24'33"E,	FL 035 ----- SOL	Survol interdit Overflight Prohibited
<b>DBP 7 COTONOU</b>  06°21'24"N - 002°24'32"E, 06°21'33"N - 002°24'45"E, 06°21'12"N - 002°24'44"E, 06°21'13"N - 002°24'31"E, 06°21'24"N - 002°24'32"E,	FL 035 ----- SOL	Survol interdit Overflight Prohibited

**MODIFIER / MODIFY eAIP ASECNA 01 - ENR 5.1**

**FIN/END**