

Phone : +(221) 77.519.79.01
 +(221) 33.957.49.37
 Fax : +(221) 33.820.06.00
 AFTN : GOOYNYX
 E-mail : bndak@asecna.org
 Web : <https://ais.asecna.aero>



AIP SUP
NR 85/A/22GO
JUNE 20 , 2022

BUREAU NOTAM INTERNATIONAL DE L' OUEST AFRICAIN
 B.P. 8155 Aéroport International Blaise DIAGNE Dakar/Diass-SENEGAL

BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER – SENEGAL – TOGO

GLIDE PATH HORS SERVICE A L' AERODROME DE NIAMTOUGOU

GLIDE PATH UNSERVICEABLE AT NIAMTOUGOU AERODROME

/

DXNG

TOGO

Mise en vigueur / <i>Effective Date</i>	20 Juin 2022, <i>June 20 2022</i>
Validité / <i>Validity</i>	31 Août 2022, <i>August 31 2022</i>

CE SUPPLEMENT ANNULE ET REMPLACE LE SUPPLEMENT NR 33/A/22GO
THIS SUPPLEMENT CANCELS AND REPLACES THE SUPPLEMENT NR 33/A/22GO

AERODROME / <i>AERODROME</i>	TYPE D'AIDE/ TYPE OF AID	FREQUENCES (MHZ- KHZ) / FREQUENCY	ETAT/ <i>STATUS</i>
NIAMTOUGOU	ILS/GP 03	335 MHz	HORS SERVICE / <i>UNSERVICEABLE</i>

FIN / *END*