

Phone : +(221) 77.519.79.01
 +(221) 33.957.49.37
 Fax : +(221) 33.820.06.00
 AFTN : GOOYNYX
 E-mail : bnidak@asecna.org
 Web : <https://ais.asecna.aero>



AIP SUP
NR 18/A/23GO
FEBRUARY 14 , 2023

BUREAU NOTAM INTERNATIONAL DE L'OUEST AFRICAIN
 B.P. 8155 Aéroport International Blaise DIAGNE Dakar/Diass-SENEGAL

BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER – SENEGAL – TOGO

GLIDE PATH HORS SERVICE A L'AERODROME DE NIAMTOUGOU
GLIDE PATH UNSERVICEABLE AT NIAMTOUGOU AERODROME

/
DXNG
TOGO

Mise en vigueur / Effective Date	14 Février 2023, February 14 2023
Validité / Validity	31 Décembre 2023, December 31 2023

CE SUPPLEMENT ANNULE ET REMPLACE LE SUPPLEMENT NR 127/A/22GO
THIS SUPPLEMENT CANCELS AND REPLACES THE SUPPLEMENT NR 127/A/22GO

AERODROME / AERODROME	TYPE D'AIDE / TYPE OF AID	FREQUENCES (MHZ-KHZ) / FREQUENCY	ETAT / STATUS
NIAMTOUGOU	ILS/GP 03	335 MHz	HORS SERVICE / UNSERVICEABLE

FIN / END