

Tel : +(261) 20.22.581.13
 +(261) 20.22.581.14
 +(261) 33.23.370.01

Fax : NIL

AFTN : FMMYNYX

E-mail : bnitan@asecna.org
 AntananarivoNOF@gmail.com

Web : <https://aim.asecna.aero>



**BUREAU NOTAM INTERNATIONAL
 D'ANTANANARIVO**

**B.P. 46 Ivato Aéroport Antananarivo -
 MADAGASCAR**

**AIP SUP
 NR 24/B/23FM
 19 OCT 2023**

LA REUNION* - MADAGASCAR - MAYOTTE* - UNION DES COMORES

* The AIC, AMDT, AIP and AIP SUP concerning these islands are published on <https://sia.aviation-civile.gouv.fr>

FMSM

**ETAT DE L'INSTALLATION AIR/SOL 5484KHZ (U/S)
 STATUS OF THE A/G FAC 5484KHZ (U/S)**

<i>Effective date :</i>	19 OCT 2023
<i>Validity :</i>	30 JUN 2025 EST

L'installation air/sol listée dans le tableau ci-après est **hors service** :

The air/ground facility listed in the following table is **unserviceable** :

LOCATION	SERVICE	FREQUENCY	STATUS
MANANJARY (FMSM)	AFIS	5484KHZ	U/S

Remarque : Le présent SUP AIP est publié suite à l'atelier organisé par l'OACI en juin 2021 sur l'amélioration des NOTAM, qui vise à diminuer la prolifération des NOTAM dans la région ESA. Ainsi l'information contenue dans le NOTAM B0333/23 qui concerne l'aérodrome de MANANJARY est incorporée dans le présent SUP AIP.

Remark : This SUP AIP is published following the workshop organized by ICAO in June 2021 on improving NOTAM, that aims to reduce the proliferation of NOTAM in the ESAF region. Thus information contained in the NOTAM B0333/23 that concerns MANANJARY aerodrome is incorporated in this AIP SUP.

THIS AIP SUP HAS 01 PAGE