

Tel : +(261) 20.76.581.13
 +(261) 33.23.370.01
 Fax : NIL
 AFTN : FMMMYNYX
 E-mail : aim-fmmm@asecna.org
 AntananarivoNOF@gmail.com
 Web : https://aim.asecna.aero



**BUREAU NOTAM INTERNATIONAL
 D'ANTANANARIVO**
 B.P. 46 Ivato Aéroport Antananarivo -
 MADAGASCAR

**AIP SUP
 NR 31/B/24FM
 24 OCT 2024**

LA REUNION* - MADAGASCAR - MAYOTTE* - UNION DES COMORES

* The AIC, AMDT, AIP and AIP SUP concerning these islands are published on <https://sia.aviation-civile.gouv.fr>

FMMV

ERECTION DE L'OBSTACLE « BATIMENT »
ERECTION OF THE BUILDING OBSTACLE

<i>Effective date :</i>	24 OCT 2024
<i>Validity :</i>	31 DEC 2025 EST

L'obstacle dont les caractéristiques figurent dans le tableau ci-après reste érigé à l'aérodrome de Morondava :

The obstacle whose characteristics are shown in the following table remains erected at Morondava aerodrome :

ZONE Area	IDENTIFICATION OU DESIGNATION obstacle/identification or designation	TYPE D'OBSTACLE Type of Obstacle	COORDONNÉES Coordinates	ALTITUDE / HAUTEUR (mètres) elevation/height (in Meters)	MARQUAGES, TYPE ET COULEUR DU BALISAGE LUMINEUX obstacle marking, type and color of obstacle lighting	OBSERVATIONS Remarks
0	1	2	3	4	5	6
Zone 2	Bâtiment	Building	20°17'05.5"S 044°18'42.8"E	15.5M 8.5M AGL	Unmarked - Unlighted	Erected at 305M from THR 10

Remarque : Le présent SUP AIP est publié suite à l'atelier organisé par l'OACI en juin 2021 sur l'amélioration des NOTAM, qui vise à diminuer la prolifération des NOTAM dans la région ESA. Ainsi l'information contenue dans le NOTAM B0228/24 qui concerne l'aérodrome de MORONDAVA est incorporée dans le présent SUP AIP.

Remark : This SUP AIP is published following the workshop organized by ICAO in June 2021 on improving NOTAM, that aims to reduce the proliferation of NOTAM in the ESAF region. Thus information contained in the NOTAM B0228/24 that concerns MORONDAVA aerodrome is incorporated in this AIP SUP.

THIS AIP SUP HAS 01 PAGE