

Phone : +(221)33.957.49.37
 +(221) 77.519.79.01
 Fax : +(221) 33.820.06.00
 AFTN : GOOYNYX
 E-mail : bnidakar@asecna.org
 Web : <https://aim.asecna.aero>



AIP SUP
NR15/A/20GO
MARCH 09 , 2020

BUREAU NOTAM INTERNATIONAL DE L'OUEST AFRICAIN
 B.P. 8155 Aéroport International Blaise DIAGNE Dakar/Diass-SENEGAL

BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER–SENEGAL–TOGO

MISE A JOUR DES INFORMATIONS AERONAUTIQUES DE L'AERODROME DE YELIMANE

UPDATE OF AERONAUTICAL INFORMATION OF YELIMANE AERODROME

/
MALI

mise en vigueur /effective date	09 mars 2020/march 09, 2020
Validite /validity	PERM

Zone Area	Identification ou designation obstacle identification or designation	Types Type of obstacle	Position obstacle position	Altitude Hauteur Elevation Height	Marquages, type et couleur du balisage lumineux obstacle marking, and type and color of obstacle lighting	Disponibilité électronique electricity availability
	1	2	3	4	5	6
2a	Antenna	Antenna	15°06'48.4"N 10°34'10.6" W	149.2 M 48 M	- Marked - Red lighted	NIL
	Antenna	Antenna	15°07'15.5"N 010°34'27.3" W	148.1 M 47 M	-Marked -Red lighted	NIL
	Mosque	building	15°07'15.9"N 010°34'20.2" W	116.9 M 16 M	-Unmarked -Unlighted	NIL
2b	Immeuble	building	15°07'28.5"N 010°34'47.1"W	107 M 8 M	-Unmarked -Unlighted	NIL
	Immeuble	building	15°07'29.0"N 010°34'48.2"W	107 M 8 M	-Unmarked -Unlighted	NIL

Modifiez/modify: 10AD2-GAYE-VAC; 10AD2-GAYE-VLC

FIN/END