

Phone : +(221) 33.869.23.32  
 +(221) 33.869.23.46  
 Fax : +(221) 33.820.06.00  
 AFTN : GOOOYNYX  
 E-mail : senegalbni@asecna.org  
 Web : [www.ais-asecna.org](http://www.ais-asecna.org)



**AIRAC AIP SUP  
 NR 70/A/23GO  
 SEPT 30<sup>th</sup>, 2023**

**BUREAU NOTAM INTERNATIONAL DE L'OUEST AFRICAIN**  
 B.P. 8155 Aéroport International Léopold Sédar SENGHOR Dakar/Yoff-SENEGAL

**BENIN – BURKINA FASO – COTE D'IVOIRE – GUINEE BISSAU – MALI – MAURITANIE – NIGER–SENEGAL–TOGO**

**CREATION D'UN NOUVEAU POINT 5LNC EN REMPLACEMENT DU NDB SLO EN FIR  
 DAKAR**

*CREATION OF A NEW 5LNC POINT REPLACING THE NDB SLO IN FIR DAKAR*

<b>Mise en vigueur / Effective date</b>	<b>30 Novembre 2023, November 30<sup>th</sup> 2023</b>
<b>Validité / Validity</b>	<b>PERM</b>

<p><b>I. INTRODUCTION</b></p> <p>À compter de la date AIRAC du 30 novembre 2023, le point 5LNC est créé dans la TMA et UTA de Dakar sur les routes R975 et U975 en remplacement du NDB SLO (Saint Louis) qui a été mis hors service conformément au tableau ci-dessous.</p> <p>Les caractéristiques dudit point sont consignées dans le tableau ci-dessous.</p>	<p><b>I. INTRODUCTION</b></p> <p><i>As of the AIRAC date of November 30, 2023, the 5LNC point within Dakar TMA and UTA is created on the ATS routes R975 and U975 to replace the NDB SLO (Saint Louis) which was decommissioned in accordance with the table below.</i></p> <p><i>The characteristics of this point are set out in the table below.</i></p>
<p><b>II. MODIFICATIONS</b></p> <p>Modifier AIP: GEN 2.5, ENR 1.8, ENR4.1, ENR 4.4, ENR6.1, ENR 6.2.</p>	<p><b>II. CHANGES</b></p> <p><i>Modify AIP: GEN 2.5, ENR 1.8, ENR4.1, ENR 4.4, ENR6.1, ENR 6.2.</i></p>

<b>Former Point</b>	<b>New point</b>	<b>Geographic coordinates</b>	<b>ATS Route</b>	<b>Descriptions</b>
<b>SLO</b>	<b>SAKLI</b>	<b>160256.70N 0162725.70W</b>	<b>R975- U975</b>	<b>Point within Dakar TMA and UTA</b>

**FINI/END**  
**CE SUPPLÉMENT AIP COMPORTE 01 PAGE**  
**THIS SUPPLEMENT AIP INCLUDES 01 PAGE**